



Theoretical values

Normal Probe Mode
Measured values

Fast Probe Mode
Measured values

Fast Probe: probing mode applies to analog scanning probes when taking individual hits rather than scanning. When it is ON, it provides a significant reduction in the time required to take individual hits. The biggest reduction in time occurs when the probe retracts from the part.

